

NATIONAL PHYSICAL LABORATORY
Time and Frequency Services
Division for Enabling Metrology
Teddington, Middx, United Kingdom TW11 0LW

Telephone: 020 8943 6880
Facsimile: 020 8943 6458
E-mail: time@npl.co.uk

N P L D R O I T W I C H B u l l e t i n

No.06-09 September 2006

MJD	Date	UTC(NPL)-Droitwich(198 kHz) 12h UTC (microseconds)	UTC(NPL)-Droitwich(198 kHz) 15h UTC (microseconds)
53979	2006-09-01	-516.7	-516.6
53980	2006-09-02	-516.6	-516.5
53981	2006-09-03	-516.4	-516.3
53982	2006-09-04	-516.2	-516.1
53983	2006-09-05	-516.1	-516.0
53984	2006-09-06	-516.1	-516.1
53985	2006-09-07	-516.1	-516.0
53986	2006-09-08	-515.9	-515.8
53987	2006-09-09	-515.7	-515.6
53988	2006-09-10	-515.5	-515.4
53989	2006-09-11	-515.5	-515.4
53990	2006-09-12	-515.6	-515.6
53991	2006-09-13	-515.7	-515.7
53992	2006-09-14	-515.7	-515.7
53993	2006-09-15	-515.6	-515.5
53994	2006-09-16	-515.4	-515.3
53995	2006-09-17	-515.2	-515.1
53996	2006-09-18	-515.1	-515.0
53997	2006-09-19	-515.0	-514.9
53998	2006-09-20	-514.7	-514.7
53999	2006-09-21	-514.5	-514.4
54000	2006-09-22	-514.5	-514.5
54001	2006-09-23	-514.4 (a)	-514.3 (a)
54002	2006-09-24	-514.2	-514.1
54003	2006-09-25	-514.0	-514.0
54004	2006-09-26	-513.9	-513.8
54005	2006-09-27	-513.6	-513.6
54006	2006-09-28	-513.8	-513.8
54007	2006-09-29	-513.6	-513.6
54008	2006-09-30	-513.4	-513.3

(a) at least one interruption in received carrier since the previous reading

(b) at least one discontinuity in received phase since the previous reading

reading not available